






μ -X360J

Retained Austenite Measurement (Optional function)

Measure the percentage of retained austenite not transformed to martensite upon quenching.

Non-contact and non-destructive measurement using the X-ray diffraction technique.

Measurement result



Results of 500 orientation can output at one measurement!

High repeatable measurement by averaging full ring data: 500 results