


μ -X360s Application

Check the Annealing Effect

“Annealing” is a heat treatment to remove residual stress, soften metal structure and reduce strains.

Possible to check heat treatment effect with non-contact and non-destructive measurement!

Residual stress and FWHM before and after annealing near weld area



Improve the material properties by optimum heat treatment condition!